

APPENDIX C PHOTOLOG



Photopoint 1. Overview of Slope



Photopoint 2. No beds, no banks, no stream present on NHD line.



Photopoint 3. Ephemeral drainage, upland vegetation with no sign of water. EPH100.



Photopoint 4. Ephemeral drainage, upland vegetation with no sign of water. EPH100.



Photopoint 5. Erosional feature. EPH101.



Photopoint 6. Erosional feature. EPH102.



Photopoint 7. No beds, no banks, no stream present on NHD line.



Photopoint 8. Streambed with watermarks on rocks, and water in pools due to recent rainfall. INT01.



Photopoint 9. Streambed with watermarks on rocks, and water in pools due to recent rainfall. INT01.



Photopoint 10. Streambed with watermarks on rocks, and water in pools due to recent rainfall. INT01.



Photopoint 11. Water in pools due to recent rainfall. INT01.



Photopoint 12. Waterline on rocks. INT01.



Photopoint 14. No beds, no banks, no stream present on NHD line.



Photopoint 15. Ephemeral drainage, upland vegetation with no sign of water. EPH105.



Photopoint 16. Ephemeral drainage, upland vegetation with no sign of water. Yarrow in channel. EPH105.



Photopoint 18. Ephemeral drainage, upland vegetation with no sign of water. EPH104.



Photopoint 19. Ephemeral drainage, upland vegetation with no sign of water. EPH105.



Photopoint 20. Ephemeral drainage, upland vegetation with no sign of water. EPH205.



Photopoint 21. No beds, no banks, no stream present on NHD line.



Photopoint 22. Ephemeral drainage, upland vegetation with no sign of water. EPH202.



Photopoint 23. Ephemeral drainage, upland vegetation with no sign of water. EPH203.



Photopoint 24. Well in bedrock in stream bottom.



Photopoint 25. No beds, no banks, no stream present on NHD line.



Photopoint 26. No beds, no banks, no stream present on NHD line.



Photopoint 27. No beds, no banks, no stream present on NHD line.



Photopoint 28. No beds, no banks, no stream present on NHD line.



Photopoint 29. No beds, no banks, no stream present on NHD line.



Photopoint 30. No beds, no banks, no stream present on NHD line.



Photopoint 31. No beds, no banks, no stream present on NHD line.



Photopoint 32. No beds, no banks, no stream present on NHD line.



Photopoint 33. No beds, no banks, no stream present on NHD line.



Photopoint 35. Garbage dump.



Photopoint 36. Ephemeral drainage, upland vegetation with no sign of water. EPH200.



Photopoint 38. No beds, no banks, no stream present on NHD line.



Photopoint 39. No beds, no banks, no stream present on NHD line.



Photopoint 41. Soil sample site. SS01.



Photopoint 42. No beds, no banks, no stream present on NHD line.



Photopoint 43. No beds, no banks, no stream present on NHD line.



Photopoint 44. No beds, no banks, no stream present on NHD line.



Photopoint 45. No beds, no banks, no stream present on NHD line.



Photopoint 46. No beds, no banks, no stream present on NHD line.



Photopoint 47. No beds, no banks, no stream present on NHD line.



Photopoint 48. No beds, no banks, no stream present on NHD line.



Photopoint 49. No beds, no banks, no stream present on NHD line.



Photopoint 50. Erosional Feature. EPH305.



Photopoint 51. No beds, no banks, no stream present on NHD line.



Photopoint 52. No beds, no banks, no stream present on NHD line.



Photopoint 53. No beds, no banks, no stream present on NHD line.



Photopoint 54. No beds, no banks, no stream present on NHD line.



Photopoint 55. No beds, no banks, no stream present on NHD line.



Photopoint 56. No beds, no banks, no stream present on NHD line.



Photopoint 57. No beds, no banks, no stream present on NHD line.



Photopoint 58. No beds, no banks, no stream present on NHD line.



Photopoint 59. Soil Sample Site. SS02.



Photopoint 60. Streambed with damp soils. INT02.



Photopoint 61. Streambed with damp soils. INT02.



Photopoint 62. Streambed with damp soils. INT02.



Photopoint 63. Streambed with damp soils. INT02.



Photopoint 64. Streambed with damp soils. INT02.



Photopoint 65. Ephemeral drainage, upland vegetation with no sign of water. EPH412.



Photopoint 67. No beds, no banks, no stream present on NHD line.



Photopoint 68. No beds, no banks, no stream present on NHD line.



Photopoint 69. No beds, no banks, no stream present on NHD line.



Photopoint 70. No beds, no banks, no stream present on NHD line.



Photopoint 71. No beds, no banks, no stream present on NHD line.



Photopoint 72. Ephemeral drainage, upland vegetation with no sign of water. EPH301.



Photopoint 73. No beds, no banks, no stream present on NHD line.



Photopoint 74. Ephemeral drainage, upland vegetation with no sign of water. EPH300.



Photopoint 75. No beds, no banks, no stream present on NHD line.



Photopoint 76. No beds, no banks, no stream present on NHD line.



Photopoint 77. No beds, no banks, no stream present on NHD line.



Photopoint 78. Ephemeral drainage, upland vegetation with no sign of water. EPH308.



Photopoint 79. Ephemeral drainage, upland vegetation with no sign of water. EPH308.



Photopoint 80. No beds, no banks, no stream present on NHD line.



Photopoint 81. Ephemeral drainage, upland vegetation with no sign of water. EPH308.



Photopoint 82. No beds, no banks, no stream present on NHD line.



Photopoint 83. Ephemeral drainage, upland vegetation with no sign of water. EPH307.



Photopoint 84. No beds, no banks, no stream present on NHD line.



Photopoint 85. Ephemeral drainage, upland vegetation with no sign of water. EPH307.



Photopoint 86. No beds, no banks, no stream present on NHD line.



Photopoint 87. Ephemeral drainage, upland vegetation with no water. EPH307.



Photopoint 88. Ephemeral drainage, upland vegetation with no sign of water. EPH306.



Photopoint 89. No beds, no banks, no stream present on NHD line.



Photopoint 90. Ephemeral drainage, upland vegetation with no sign of water. EPH401.



Photopoint 91. No beds, no banks, no stream present on NHD line.



Photopoint 93. Streambed with watermarks on rocks, and water in pools due to recent rainfall. INT01.



Photopoint 94. Ephemeral drainage, upland vegetation with no sign of water. EPH400.



Photopoint 95. Ephemeral drainage, upland vegetation with no sign of water. EPH400.



Photopoint 96. Ephemeral drainage, upland vegetation with no sign of water. EPH303.



Photopoint 97. Ephemeral drainage, upland vegetation with no sign of water. EPH303.



Photopoint 98. No beds, no banks, no stream present on NHD line.



Photopoint 99. No beds, no banks, no stream present on NHD line. Road present in valley bottom.



Photopoint 100. No beds, no banks, no stream present on NHD line.



Photopoint 101. No beds, no banks, no stream present on NHD line.



Photopoint 102. Ephemeral drainage, upland vegetation with no sign of water. EPH405.



Photopoint 103. Ephemeral drainage, upland vegetation with no sign of water. EPH404.



Photopoint 104. Ephemeral drainage, upland vegetation with no sign of water. EPH405.



Photopoint 105. Ephemeral drainage, upland vegetation with no sign of water. EPH404.



Photopoint 107. No beds, no banks, no stream present on NHD line.



Photopoint 108. No beds, no banks, no stream present on NHD line.



Photopoint 109. No beds, no banks, no stream present on NHD line.



Photopoint 110. No beds, no banks, no stream present on NHD line.



Photopoint 111. No beds, no banks, no stream present on NHD line.



Photopoint 114. No beds, no banks, no stream present on NHD line.



Photopoint 115. No beds, no banks, no stream present on NHD line.



Photopoint 209. No beds, no banks, no stream present on NHD line.



Photopoint EPH104. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint EPH104. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint EPH500 levee 1. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint EPH500 N. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint EPH500 NE1. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint EPH501 NW1. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint EPH501 SE. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint EPH501 SE1. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint EPH500 levee 2. Ephemeral drainage, upland vegetation with no sign of water.



Photopoint XBB 310. No beds, no banks, no stream present on NHD line.



Photopoint XBB 300. No beds, no banks, no stream present on NHD line.



Photopoint XBB 301. No beds, no banks, no stream present on NHD line.



Photopoint XBB 302. No beds, no banks, no stream present on NHD line.



Photopoint XBB 303. No beds, no banks, no stream present on NHD line.



Photopoint XBB 304. No beds, no banks, no stream present on NHD line.



Photopoint XBB 305. No beds, no banks, no stream present on NHD line.



Photopoint XBB 306. No beds, no banks, no stream present on NHD line.



Photopoint XBB 307. No beds, no banks, no stream present on NHD line.



Photopoint XBB 308. No beds, no banks, no stream present on NHD line.



Photopoint XBB 309. No beds, no banks, no stream present on NHD line.



Photopoint XBB 310. No beds, no banks, no stream present on NHD line.



Photopoint XBB 311. No beds, no banks, no stream present on NHD line.



Photopoint XBB 312. No beds, no banks, no stream present on NHD line.



Photopoint XBB 313. No beds, no banks, no stream present on NHD line.



Photopoint 600. Ephemeral drainage, upland vegetation with no sign of water . Overview of drainage, EPH401.



Photopoint 601. Ephemeral drainage, upland vegetation with no sign of water Ephemeral drainage, EPH401.



Photopoint 602. Ephemeral drainage, upland vegetation with no sign of water Ephemeral stream does not extend uphill. EPH306.



Photopoint 603. Ephemeral drainage, upland vegetation with no sign of water Ephemeral drainage, less than one foot wide. EPH306.



Photopoint 604. No beds, no banks, no stream present on NHD line. Cattle trail.



Photopoint 605. No beds, no banks, no stream present on NHD line. Ephemeral stream does not extend beyond this point.



Photopoint 606. No beds, no banks, no stream present on NHD line.



Photopoint 607. Ephemeral drainage, upland vegetation with no sign of water. Narrow ephemeral drainage, EPH600.



Photopoint 608. Ephemeral drainage, upland vegetation with no sign of water. Overview of EPH600.



Photopoint 609. No beds, no banks, no stream present on NHD line.



Photopoint 610. No beds, no banks, no stream present on NHD line. Culvert under road.



Photopoint 611. Ephemeral drainage, upland vegetation with no sign of water. Ephemeral drainage begins at this point, EPH602.



Photopoint 612. Ephemeral drainage, upland vegetation with no sign of water. EPH602.



Photopoint 613. End of EPH602.



Photopoint 614. No beds, no banks, no stream present on NHD line.



Photopoint 701. Ephemeral drainage, upland vegetation with no sign of water. EPH401.



Photopoint 702. No beds, no banks, no stream present on NHD line. Upstream end of EPH401.



Photopoint 703. Ephemeral drainage, upland vegetation with no sign of water. EPH401.



Photopoint 704. Ephemeral drainage, upland vegetation with no sign of water. EPH401.



Photopoint 705. No beds, no banks, no stream present on NHD line. Hillside between plowed fields.



Photopoint 706. No beds, no banks, no stream present on NHD line.



Photopoint 708. Ephemeral drainage, upland vegetation with no sign of water Ephemeral drainage, with trash pile. EPH306.



Photopoint 709. No beds, no banks, no stream present on NHD line.



Photopoint 710. No beds, no banks, no stream present on NHD line.



Photopoint 711. No beds, no banks, no stream present on NHD line.



Photopoint 712. No beds, no banks, no stream present on NHD line.



Photopoint 713. No beds, no banks, no stream present on NHD line. Bottom between two hills next to freeway.



Photopoint 714. No beds, no banks, no stream present on NHD line.



Photopoint 715. No beds, no banks, no stream present on NHD line.



Photopoint 716. No beds, no banks, no stream present on NHD line.



Photopoint 717. No beds, no banks, no stream present on NHD line.



Photopoint 718. No beds, no banks, no stream present on NHD line.



Photopoint 719. No beds, no banks, no stream present on NHD line.



Photopoint 720. Ephemeral drainage, upland vegetation with no sign of water. EPH700.



Photopoint 721. Ephemeral drainage, upland vegetation with no sign of water. EPH700, leading up to culvert under road.



Photopoint 722. No beds, no banks, no stream present on NHD line.



Photopoint 723. Ephemeral drainage, upland vegetation with no sign of water. EPH700.



Photopoint 724. Ephemeral drainage, upland vegetation with no sign of water. Upstream end of EPH700, begins to lose bed and banks.



Photopoint 725. No beds, no banks, no stream present on NHD line.



Photopoint 800. No beds, no banks, no stream present on NHD line. Water retention pond, with no culvert.



Photopoint 801. No beds, no banks, no stream present on NHD line.



Photopoint 802. No beds, no banks, no stream present on NHD line.



Photopoint 803. No beds, no banks, no stream present on NHD line.



Photopoint 804. No beds, no banks, no stream present on NHD line.



Photopoint 805. No beds, no banks, no stream present on NHD line.



Photopoint 806. No beds, no banks, no stream present on NHD line.



Photopoint 807. No beds, no banks, no stream present on NHD line.



Photopoint 808. No beds, no banks, no stream present on NHD line.



Photopoint 809. No beds, no banks, no stream present on NHD line.



Photopoint 810. No beds, no banks, no stream present on NHD line.



Photopoint 811. Ephemeral drainage, upland vegetation with no sign of water, EPH800.



Photopoint 812. Ephemeral drainage, upland vegetation with no sign of water, EPH800.



Photopoint 813. No beds, no banks, no stream present on NHD line. No culvert alongside road.



Photopoint 814. No beds, no banks, no stream present on NHD line.



Photopoint 900. No beds, no banks, no stream present on NHD line.



Photopoint 900b. Ephemeral drainage, typical conditions. EPH-900. Facing southwest.



Photopoint 900c. Ephemeral drainage. EPH-900. No bed or banks southwest of here.



Photopoint 904. Ephemeral drainage, typical conditions. EPH-904. Facing northwest.



Photopoint 904a. Ephemeral drainage, typical conditions. EPH-904A. Facing north.



Photopoint 905. Ephemeral drainage, typical conditions. EPH-904. Facing west.



Photopoint E10. Sample site. No water, horsetail, well pump in background.



Photopoint E10a. Overview.



Photopoint E10b. Sample site. Upland, great basin wildrye and non-hydric soils.



Photopoint E18. Sample site. Upland, cereal rye and non-hydric soils.



Photopoint 901. No beds, no banks, no stream present on NHD line. Facing northeast.



Photopoint 902. No beds, no banks, no stream present on NHD line. Facing northeast.